

Volvo Trucks North America, Inc.

Greensboro, NC USA


TSI

This TSI Service Bulletin replaces the following TSI Service Manual Supplements: 200–750–01, "Intermediate Gear, Higher Torque" (11.99), publication no. PV776–200–750–01SB; 200–760–01, "Intermediate Gear, Higher Torque" (11.99), publication no. PV776–200–760–01SB; and 200–770–01, "Intermediate Gear, Higher Torque" (11.99), publication no. PV776–200–770–01SB.

Date Group No. Supp. Page 12.2001 **215 008** 1(2)

Intermediate Gear Tightening Torque TD122, TD123

Intermediate Gear



T2012748

(Effective from February 1999)

A higher torque is specified for the nut for the intermediate gear on TD122 and TD123 engines.

Contents

"Intermediate Gear Tightening Torque" page 2

PV776-TSP161567 USA10459

Specifications

Intermediate Gear Tightening Torque

When servicing the intermediate gear bearing, note these modifications:

- A new nut is used to install the intermediate gear. It should be installed with the flat surface against the ball bearing. This nut no longer uses a washer and lock ring. (See Fig. 1: installing intermediate gear, page 2.)
- The new nut should be torque-tightened to 190 ± 10
 Nm (140 ± 8 ft-lb) using pin spanner 9996682. (See Fig. 2: 9996682, pin spanner, page 2.)




Fig. 1: installing intermediate gear

T2012748




Fig. 2: 9996682, pin spanner